

# Imray Correction Notice

ICC28-1

13 September 2012

## Chart C28 WGS 84

*Edition Apr 2010*

*Date of printing Apr 2010*

The following corrections should be noted:

### 1 Blakeney Overfalls northeastwards

Delete Y spher Lt buoy FI(5)Y.20s in 53°03'·7N 1°02'·1E (ILNW 193/10)

### 2 Sheringham Shoal westwards

Insert Gy spher Lt buoy FI(5)Y.20s in 53°03'·37N 1°06'·67E (ILNW 194/10)

### 3 Wells-next-the-Sea (Main chart & Plan A)

Move **Wells Harbour** FI(2)R.5s Lt buoy to 52°59'·64N 0°50'·74E (ILNW 238/10)

### 4 Winterton-on-Sea

Delete racon sym + assoc. lgd at church tower in 52°42'·92N 1°41'·21E (ILNW 402/10)

### 5 Approaches to Great Yarmouth (*correction amended - see ILNW 140/12*)

Move Lt buoys:

**Scroby Elbow** FI(2)G.5s to 52°36'·55N 1°46'·26E

**SW Scroby** FI.G.2.5s to 52°35'·13N 1°46'·69E

**Holm** FI.G.2.5s to 52°33'·62N 1°48'·01E (and rename **Mid Corton**)

**S Corton** Q(6)+LFI.15s to 52°32'·94N 1°49'·12E

**NE Holm** FI.R.2.5s to 52°32'·68N 1°48'·48E

**Holm Sand** Q to 52°33'·93N 1°47'·23E (and remove **N Holm**)

**Corton** Q(3)10s to 52°30'·88N 1°50'·22E (rename **Holm Approach** and delete *Whis*)

Delete Lt buoys:

**W Corton** Q(9)15s in 52°34'·59N 1°46'·61E

**E Holm** FI(3)R.10s in 52°30'·45N 1°50'·00E

Insert Lt buoys:

G con **W Corton** FI(3)G.10s in 52°34'·12N 1°47'·50E

W card pillar **Holm Sand** Q(9)15s in 52°33'·18N 1°46'·54E (ILNW 427/10)

### 6 Aldeburgh Ridge (Main & Plan F)

Move **Aldeburgh Ridge** Q.R Lt buoy to 52°06'·49N 1°36'·95E (ILNW 447/10)

### 7 Environment Agency buoyage

Delete Y spar Lt buoys FI(5)Y.20s in:

52°57'·80N 1°04'·80E

52°45'·51N 1°39'·74E

52°22'·12N 1°42'·75E

52°17'·19N 1°38'·57E

52°07'·76N 1°35'·80E (ILNW 35/11)

### 8 Aldeburgh southwards (Plan F)

Delete Y spar Lt buoy **15** FI(5)Y.20s in 52°07'·76N 1°35'·80E (ILNW 36/11)

### 9 Great Yarmouth (Plan C)

Insert sym Horn(3)60s SS(INT) in 52°34'·38N 1°44'·35E.

Delete lgd Horn(3)60s SS(INT) at Lt in 52°34'·33N 1°44'·28E (ILNW 72/11)

### 10 Great Yarmouth, Outer Harbour (Plan C)

Insert lgd *Works in progress (2011)* centred on 52°34'·65N 1°44'·70E (ILNW 306/11)

### 11 Lowestoft Approaches (Main chart & Plan D)

Delete Lt FI.R.5s5m3M at Claremont Pier in 52°27'·91N 1°44'·88E (ILNW 322/11)

### 12 Orfordness

Delete Igd AIS at Orfordness lighthouse in 52°05'·03N 01°34'·46E (ILNW 56/12)

**13 Approaches to Great Yarmouth**

Amend name of N card Lt buoy **Holm Sand** to **N Holm** in 52°33'·93N 1°47'·23E (ILNW 140/12)

**14 Woodbridge Haven (Plan G)**

The 2012 positions of the River Deben entrance buoyage is as follows:

**Woodbridge Haven** Mo(A)15s in 51°58'·10N 1°23'·70E

**West Knoll** in 51°58'·36N 1°23'·47E

**Mid Knoll** in 51°58'·76N 1°23'·41E

For detailed information about the Deben entrance, mariners are advised to consult the latest sketchmap on [www.eastcoastrivers.com](http://www.eastcoastrivers.com) (ILNW 173/12)

**15 Orford Haven (Plan F)**

The 2012 positions of the River Ore entrance buoyage is as follows:

**Orford Haven** in 52°01'·85N 1°28'·21E

**Oxley** in 52°02'·15N 1°27'·80E

**Weir** in 52°02'·42N 1°27'·65E

The River Ore entrance has changed quite significantly since the last edition of this chart. Mariners are therefore advised to consult the sketchmap on [www.eastcoastrivers.com](http://www.eastcoastrivers.com) for the latest information. (ILNW 174/12)

**16 Happisburgh eastwards**

Insert Y spher Lt buoy *Waverider* Fl(5)Y.20s in 52°49'·57N 1°32'·99E (ILNW 177/12)

**17 Lowestoft Harbour (Plan H)**

Amend Lt Fl.R.3s to 2F.R(ver) in 52°28'·40N 1°45'·34E (ILNW 403/12)